

Governor GARY R. HERBERT Lieutenant Governor

### State of Utah DEPARTMENT OF NATURAL RESOURCES Division of Oil, Gas & Mining

MICHAEL R. STYLER Executive Director

JOHN R. BAZA Division Director

### **Inspection Report** Minerals Regulatory Program Report Date November 23, 2005

Supervisor

Mine Name:	Last	t Chance	Clay Mine
<b>Operator Na</b>	me:	Western	Clav

Permit number: M/015/061

Inspection Date: November 22, 2005

Time: 1:00-1:30 PM

Inspector(s): Paul Baker Other Participants: None Mine Status: Inactive

Weather: Clear, 50's

<b>Elements of Inspection</b>	Evaluated	Comment	Enforcement
<ol> <li>Permits, Revisions, Transfer, Bonds</li> <li>Public Safety (shafts, adits, trash, signs, highwalls)</li> <li>Protection of Drainages / Erosion Control</li> <li>Deleterious Material</li> <li>Roads (maintenance, surfacing, dust control, safety)</li> <li>Concurrent Reclamation</li> <li>Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)</li> <li>Water Impoundments</li> <li>Soils</li> <li>Revegetation</li> </ol>			
<ul><li>11. Air Quality</li><li>12. Other</li></ul>			
Purpose of Inspection:			

This was a routine inspection with no predetermined purpose.

### **Inspection Summary:**

10. Revegetation

North of the mine, there were previously several flagged individuals of *Pediocactus winkleri*, a threatened species. I had seen the flags and these plants in inspections the last two years, but I was not able to find any during this inspection. It is not surprising that I could not find plants because they are extremely difficult to see except when they are blooming, but I expected to find the flags marking the locations of the plants. It is possible the flags are deteriorated to the point that they are difficult to find and that I didn't look hard enough.

### 12. Other

The site has changed little, if at all, since the last time I visited a year ago. I used a GPS unit to map the disturbed area and obtained an area of 8.5 acres. The bond allows a disturbance of up to 10 acres.

### **Conclusions and Recommendations:**

When a BLM botanist is in the area, I suggest that they stop and see if the location markers for Pediocactus winkleri are truly missing and if they can find the plants.

Inspector's Signature

Date: November 23, 2005

PBB:jb

cc: Brad Boyter, Western Clay

Rebecca Doolittle, Price BLM

Attachment: GPS Map & Photos

1594 West North Temple, Suite 1210, PO Box 145801, Salt Lake City, UT 84114-5801 telephone (801) 538-5340 • facsimile (801) 359-3940 • TTY (801) 538-7458 • www.ogm.utah.gov



## ATTACHMENT

# Photographs 15/061. Last Chance Clav Mine. Western Clav Com

M/015/061, Last Chance Clay Mine, Western Clay Company Inspection Dated: November 22, 2005; Report Dated: November 23, 2005




Photo 1. View looking approximately northwest across the pit. This photo and Photo 3 make a panorama.



Photo 3.





Photo 2. Another view of part of the pit.



### Mine Number: M0150061 Mine Name: Last Chance 25 and 26 Township 25 S Range 06 E Section 7-8 SLBM

Inspection Date Nov. 22, 2005 Map Produced by DKS

Acres Disturbed 8.51
Acres Regraded 0
Acres Seeded 0
Road Acres Disturbed 0

Total Acres Distrubed 8.51

Acres Released 0
Acres Excluded 0
Acres PreExisting 0
Acres Prelaw 0

Legend

All items symbolized in legend may not be appear on map

Township or range Line

County Boundary

Township or range line: location doubtful Access

Mine

NonMine

Section fine

Section fine: location doubtful finerstate

US Route

Seeded

State Route

Seeded

State Route

Primary Route

Beddd

Prelaw

Unimproved Road


Interchange

BUMS alable Minerals

CommunityPit

CommunityPit

DOQ imagery date 1998



Dept. of Natural Resources Division of Oil, Gas, and Mining Mineral Mines Program

Resources Different

Different data sources and input scales may cause misalignment of data layers. This product may not meet DOGM standards for accuracy and content.

1:7,500 1 inch equals 625 feet

Verify Scale